

## PADRÓN DE LOS EDIFICIOS SUJETOS A INSPECCIÓN TÉCNICA EN EL AÑO 2023

UNIDAD CONSTRUCTIVA	REFERENCIA	AÑO	ANTIGUEDAD	PROT. POM
<b>AV FRANCISCO AGUIRRE,0282</b>				
0000	3057303UK4235N	1967	1967	
<b>AV FRANCISCO AGUIRRE,0409</b>				
0001	2652718UK4225S	1972	1972	
<b>AV PIO XII,0008</b>				
0000	4356003UK4245N	1972	1972	
<b>AV PIO XII,0009</b>				
0000	4655004UK4245N	1955	1955	S
<b>AV PIO XII,0011</b>				
0000	4655003UK4245N	1955	1955	S
<b>AV PIO XII,0012</b>				
0001	4357402UK4245N	1960	1960	S
0002	4357402UK4245N	1960	1960	S
<b>AV PIO XII,0013</b>				
0000	4655002UK4245N	1955	1955	S
<b>AV PIO XII,0015</b>				
0000	4655001UK4245N	1955	1955	S
<b>AV PIO XII,0017</b>				
0000	4455004UK4245N	1955	1955	S
<b>AV PIO XII,0019</b>				
0000	4455003UK4245N	1955	1955	S
<b>AV PIO XII,0021</b>				
0000	4455002UK4245N	1955	1955	S
<b>AV PIO XII,0023</b>				
0000	4455001UK4245N	1955	1955	S
<b>AV PIO XII,0037</b>				
0001	4255101UK4245N	1950	1950	
0002	4255101UK4245N	1950	1950	
<b>AV PIO XII,0061</b>				
0000	3956002UK4235N	1972	1972	
<b>AV PIO XII,0061I</b>				
0001	3956060UK4235N	1972	1972	
<b>AV PIO XII,0107</b>				
0001	3557008UK4235N	1940	1940	S
0002	3557008UK4235N	1940	1940	S
0003	3557008UK4235N	1940	1940	S
<b>AV PIO XII,0109</b>				
0000	3557007UK4235N	1967	1967	
<b>AV PORTUGAL,0049</b>				
0001	2849015UK4224N	1972	1972	
<b>AV SALVADOR ALLENDE,0006X</b>				

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0001	4652101UK4245S	1900	1900	S
<b>AV TOLEDO,0031</b>					
	0000	4255301UK4245N	1972	1972	
<b>AV TOLEDO,0035</b>					
	0001	4255102UK4245N	1950	1950	
<b>CJ HORNO,0005</b>					
	0000	3251010UK4235S	1900	1900	S
<b>CJ IDEAL,0003</b>					
	0000	3352010UK4235S	1972	1972	
<b>CJ SAN FRANCISCO,0001</b>					
	0000	3852211UK4235S	1972	1972	
<b>CJ SAN PEDRO,0003</b>					
	0001	3750006UK4235S	1900	1900	S
<b>CJ SANTO DOMINGO,0006</b>					
	0000	3353828UK4235S	1972	1972	
<b>CJ TEATRO,0002</b>					
	0001	3650002UK4235S	1958	1958	S
	0002	3650002UK4235S	1958	1958	S
	0003	3650002UK4235S	1958	1958	S
<b>CL ALAMILLO,0010</b>					
	0000	3754015UK4235S	1900	1900	S
	0000	3754015UK4235S	2008	2008	S
<b>CL ALCAUDETE,0040</b>					
	0001	3741002UK4234S	1972	1972	
	0001	3741002UK4234S	1972	1972	
<b>CL ALFARES,0003</b>					
	0000	3854107UK4235S	1972	1972	
<b>CL ALFONSO XI,0003</b>					
	0001	2752008UK4225S	1972	1972	
	0001	2752008UK4225S	1972	1972	
	0001	2752008UK4225S	1972	1972	
	0001	2752008UK4225S	1972	1972	
	0001	2752008UK4225S	1972	1972	
	0001	2752008UK4225S	1972	1972	
	0001	2752008UK4225S	1972	1972	
	0002	2752008UK4225S	1972	1972	
	0002	2752008UK4225S	1972	1972	
	0002	2752008UK4225S	1972	1972	
	0002	2752008UK4225S	1972	1972	
	0002	2752008UK4225S	1972	1972	
	0002	2752008UK4225S	1972	1972	
	0002	2752008UK4225S	1972	1972	
	0002	2752008UK4225S	1972	1972	
<b>CL ALFONSO XI,0011</b>					
	0002	2752006UK4225S	1972	1972	
	0002	2752006UK4225S	1972	1972	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	<b>CL ALFONSO XI,0015</b>				
	0001	2752004UK4225S	1972	1972	
	<b>CL ALFONSO XI,0021</b>				
	0001	2752001UK4225S	1972	1972	
	<b>CL ALMANZOR,0003X</b>				
	0001	3556101UK4235N	1976	1976	S
	<b>CL ALVARADO,0029</b>				
	0000	4560801UK4246S	1972	1972	
	<b>CL ANGEL ALCAZAR,0011A</b>				
	0000	4655005UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0011B</b>				
	0000	4655006UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0011C</b>				
	0000	4655007UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0011D</b>				
	0000	4655008UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0011E</b>				
	0000	4655014UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0013A</b>				
	0000	4655010UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0013B</b>				
	0000	4655009UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0013C</b>				
	0000	4655013UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0019A</b>				
	0000	4455005UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0019B</b>				
	0000	4455006UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0019C</b>				
	0000	4455007UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0019D</b>				
	0000	4455008UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0019E</b>				
	0000	4455014UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0021A</b>				
	0000	4455010UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0021B</b>				
	0000	4455009UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0021C</b>				
	0000	4455013UK4245N	1955	1955	S
	<b>CL ANGEL ALCAZAR,0038</b>				
	0000	4655603UK4245N	1967	1967	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL ANGEL ALCAZAR,0040</b>					
	0000	4655604UK4245N	1967	1967	
<b>CL ANTONIO SORIA,0006</b>					
	0000	3760507UK4236S	1967	1967	
<b>CL ARCO S PEDRO,0004</b>					
	0000	3651102UK4235S	1900	1900	S
<b>CL ARCO S PEDRO,0006</b>					
	0001	3651103UK4235S	1945	1945	S
	0001	3651103UK4235S	1945	1945	S
	0002	3651103UK4235S	1945	1945	S
	0002	3651103UK4235S	1945	1945	S
	0003	3651103UK4235S	1945	1945	S
	0003	3651103UK4235S	1945	1945	S
	0004	3651103UK4235S	1945	1945	S
	0004	3651103UK4235S	1945	1945	S
<b>CL ARCO S PEDRO,0007</b>					
	0001	3851025UK4235S	1900	1900	S
<b>CL ARCO S PEDRO,0010</b>					
	0001	3651501UK4235S	1900	1900	S
	0001	3651501UK4235S	1900	1900	S
	0001	3651501UK4235S	1900	1900	S
	0002	3651501UK4235S	1900	1900	S
	0002	3651501UK4235S	1900	1900	S
	0002	3651501UK4235S	1900	1900	S
<b>CL ARCO S PEDRO,0011</b>					
	0000	3851024UK4235S	1969	1969	S
<b>CL ARENAS,0007</b>					
	0001	3541005UK4234S	1972	1972	
	0001	3541005UK4234S	1972	1972	
<b>CL BANDERAS CASTILLA,0033</b>					
	0000	4554005UK4245S	1960	1960	S
<b>CL BANDERAS CASTILLA,0053</b>					
	0000	4854303UK4245S	1972	1972	
<b>CL BANDERAS CASTILLA,0055</b>					
	0000	4854302UK4245S	1972	1972	
<b>CL BANDERAS CASTILLA,0057</b>					
	0000	4854301UK4245S	1972	1972	
<b>CL BAÑO,0006</b>					
	0001	3752001UK4235S	1900	1900	S
	0002	3752001UK4235S	1900	1900	S
	0003	3752001UK4235S	1900	1900	S
<b>CL BARRAGO,0009</b>					
	0002	1850502UK4215S	1967	1967	
<b>CL BARRIO S JUAN,0003</b>					
	0000	4056005UK4245N	1972	1972	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL BELVIS JARA,0016</b>					
	0001	3742007UK4234S	1972	1972	
	0001	3742007UK4234S	1972	1972	
	0002	3742007UK4234S	1972	1972	
	0002	3742007UK4234S	1972	1972	
	0003	3742007UK4234S	1972	1972	
	0003	3742007UK4234S	1972	1972	
<b>CL CALERA,0000</b>					
	0001	2343801UK4224S	1980	1980	S
<b>CL CAÑADA DE LA SIERRA,0010</b>					
	0000	3050001UK4235S	2007	2007	S
<b>CL CAP LUQUE,0052</b>					
	0000	3660010UK4236S	1967	1967	
<b>CL CAPELLANIAS,0014</b>					
	0001	2552205UK3225S	1967	1967	
<b>CL CARMEN,0006</b>					
	0001	3251015UK4235S	2008	2008	S
<b>CL CARMEN,0009</b>					
	0001	3351601UK4235S	1920	1920	S
	0002	3351601UK4235S	1920	1920	S
	0003	3351601UK4235S	1920	1920	S
<b>CL CARNICERIAS,0004</b>					
	0001	3851002UK4235S	1935	1935	S
<b>CL CARNICERIAS,0006</b>					
	0000	3851003UK4235S	1935	1935	S
<b>CL CARNICERIAS,0008</b>					
	0001	3851004UK4235S	1950	1950	S
	0002	3851004UK4235S	1950	1950	S
<b>CL CARNICERIAS,0010</b>					
	0000	3851028UK4234N	1985	1985	S
<b>CL CERRILLO S ROQUE,0008</b>					
	0000	3754201UK4235S	1972	1972	
<b>CL CERVERA,0001</b>					
	0001	3658011UK4235N	1947	1947	S
	0001	3658011UK4235N	1947	1947	S
	0001	3658011UK4235N	1947	1947	S
	0001	3658011UK4235N	1947	1947	S
	0001	3658011UK4235N	1947	1947	S
	0001	3658011UK4235N	1947	1947	S
	0002	3658011UK4235N	1947	1947	S
	0002	3658011UK4235N	1947	1947	S
	0002	3658011UK4235N	1947	1947	S
	0002	3658011UK4235N	1947	1947	S
	0002	3658011UK4235N	1947	1947	S
	0002	3658011UK4235N	1947	1947	S

<b>SITUACIÓN</b>			<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>				
0003	3658011UK4235N		1947	1947	S
0003	3658011UK4235N		1947	1947	S
0003	3658011UK4235N		1947	1947	S
0003	3658011UK4235N		1947	1947	S
0003	3658011UK4235N		1947	1947	S
0003	3658011UK4235N		1947	1947	S
<b>CL CERVERA,0010</b>					
0001	3759511UK4235N		1972	1972	
0001	3759511UK4235N		1972	1972	
0002	3759511UK4235N		1972	1972	
0002	3759511UK4235N		1972	1972	
0003	3759511UK4235N		1972	1972	
0003	3759511UK4235N		1972	1972	
<b>CL CHARCON,0001</b>					
0001	3551108UK4235S		1900	1900	S
<b>CL CHARCON,0008</b>					
0001	3451009UK4235S		1900	1900	S
0002	3451009UK4235S		1900	1900	S
0003	3451009UK4235S		1900	1900	S
0004	3451009UK4235S		1900	1900	S
<b>CL CHARCON,0033</b>					
0001	3449003UK4234N		1910	1910	S
<b>CL COMUNEROS CASTILLA,0003A</b>					
0000	3356003UK4235N		1967	1967	
<b>CL COMUNEROS CASTILLA,0003B</b>					
0000	3356012UK4235N		1967	1967	
<b>CL COMUNEROS CASTILLA,0003C</b>					
0000	3356013UK4235N		1967	1967	
<b>CL COMUNEROS CASTILLA,0010</b>					
0000	3256303UK4235N		1972	1972	
<b>CL CONCORDIA,0006</b>					
0001	2754105UK3225S		1972	1972	
0001	2754105UK3225S		1972	1972	
0001	2754105UK3225S		1972	1972	
0001	2754105UK3225S		1972	1972	
0001	2754105UK3225S		1972	1972	
0002	2754105UK3225S		1972	1972	
0002	2754105UK3225S		1972	1972	
0002	2754105UK3225S		1972	1972	
0002	2754105UK3225S		1972	1972	
0002	2754105UK3225S		1972	1972	
<b>CL CORREDERA CRISTO,0001</b>					
0001	3651134UK4235S		1900	1900	S
0001	3651134UK4235S		1900	1900	S
0002	3651134UK4235S		1900	1900	S
0002	3651134UK4235S		1900	1900	S
0003	3651134UK4235S		1900	1900	S

<b>SITUACIÓN</b>		<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>UNIDAD CONSTRUCTIVA</b>					
0003		3651134UK4235S	1900	1900	S
0004		3651134UK4235S	1900	1900	S
0004		3651134UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0003</b>					
0001		3651133UK4235S	1900	1900	S
0001		3651133UK4235S	1900	1900	S
0002		3651133UK4235S	1900	1900	S
0002		3651133UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0005</b>					
0002		3651132UK4235S	1900	1900	S
0003		3651132UK4235S	1900	1900	S
0004		3651132UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0007</b>					
0001		3651131UK4235S	1900	1900	S
0001		3651131UK4235S	1900	1900	S
0001		3651131UK4235S	1900	1900	S
0001		3651131UK4235S	1900	1900	S
0001		3651131UK4235S	1900	1900	S
0001		3651131UK4235S	1900	1900	S
0002		3651131UK4235S	1900	1900	S
0002		3651131UK4235S	1900	1900	S
0002		3651131UK4235S	1900	1900	S
0002		3651131UK4235S	1900	1900	S
0002		3651131UK4235S	1900	1900	S
0003		3651131UK4235S	1900	1900	S
0003		3651131UK4235S	1900	1900	S
0003		3651131UK4235S	1900	1900	S
0003		3651131UK4235S	1900	1900	S
0003		3651131UK4235S	1900	1900	S
0003		3651131UK4235S	1900	1900	S
0004		3651131UK4235S	1900	1900	S
0004		3651131UK4235S	1900	1900	S
0004		3651131UK4235S	1900	1900	S
0004		3651131UK4235S	1900	1900	S
0004		3651131UK4235S	1900	1900	S
0004		3651131UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0008</b>					
0000		3652008UK4235S	2005	2005	S
<b>CL CORREDERA CRISTO,0009</b>					
0001		3651130UK4235S	1900	1900	S
0001		3651130UK4235S	1900	1900	S
0002		3651130UK4235S	1900	1900	S
0002		3651130UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0010</b>					
0000		3652009UK4235S	1920	1920	S
<b>CL CORREDERA CRISTO,0011B</b>					
0001		3651129UK4235S	1900	1900	S

<b>SITUACIÓN</b>		<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>UNIDAD CONSTRUCTIVA</b>					
0001		3651129UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0013</b>					
0001		3651128UK4235S	1900	1900	S
0002		3651128UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0015</b>					
0001		3651127UK4235S	1900	1900	S
0001		3651127UK4235S	1900	1900	S
0002		3651127UK4235S	1900	1900	S
0002		3651127UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0016</b>					
0001		3652025UK4235S	1918	1918	S
0002		3652025UK4235S	1918	1918	S
<b>CL CORREDERA CRISTO,0017</b>					
0000		3651126UK4235S	1924	1924	S
<b>CL CORREDERA CRISTO,0018</b>					
0001		3652011UK4235S	1918	1918	S
<b>CL CORREDERA CRISTO,0019</b>					
0001		3651125UK4235S	1900	1900	S
0001		3651125UK4235S	1900	1900	S
0001		3651125UK4235S	1900	1900	S
0002		3651125UK4235S	1900	1900	S
0002		3651125UK4235S	1900	1900	S
0002		3651125UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0021</b>					
0001		3651124UK4235S	1900	1900	S
0001		3651124UK4235S	1900	1900	S
0002		3651124UK4235S	1900	1900	S
0002		3651124UK4235S	1900	1900	S
0003		3651124UK4235S	1900	1900	S
0003		3651124UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0022</b>					
0002		3652013UK4235S	2000	2000	S
<b>CL CORREDERA CRISTO,0023</b>					
0001		3651123UK4235S	1900	1900	S
0001		3651123UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0025</b>					
0001		3651122UK4235S	1900	1900	S
0002		3651122UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0027</b>					
0001		3651121UK4235S	1900	1900	S
0002		3651121UK4235S	1900	1900	S
0003		3651121UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0029</b>					
0000		3651120UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0032</b>					



<b>SITUACIÓN</b>		<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>UNIDAD CONSTRUCTIVA</b>					
0001		3652017UK4235S	1920	1920	S
0002		3652017UK4235S	1920	1920	S
<b>CL CORREDERA CRISTO,0034</b>					
0001		3652018UK4235S	1900	1900	S
0002		3652018UK4235S	1900	1900	S
0003		3652018UK4235S	1900	1900	S
0004		3652018UK4235S	1900	1900	S
0005		3652018UK4235S	1900	1900	S
<b>CL CORREDERA CRISTO,0036</b>					
0000		3652019UK4235S	1930	1930	S
<b>CL CORREDERA CRISTO,0038</b>					
0001		3652020UK4235S	1919	1919	S
0001		3652020UK4235S	1919	1919	S
0001		3652020UK4235S	1919	1919	S
0001		3652020UK4235S	1919	1919	S
0001		3652020UK4235S	1919	1919	S
0001		3652020UK4235S	1919	1919	S
0001		3652020UK4235S	1919	1919	S
0001		3652020UK4235S	1919	1919	S
0001		3652020UK4235S	1919	1919	S
0001		3652020UK4235S	1919	1919	S
0001		3652020UK4235S	1919	1919	S
0002		3652020UK4235S	1919	1919	S
0002		3652020UK4235S	1919	1919	S
0002		3652020UK4235S	1919	1919	S
0002		3652020UK4235S	1919	1919	S
0002		3652020UK4235S	1919	1919	S
0002		3652020UK4235S	1919	1919	S
0002		3652020UK4235S	1919	1919	S
0002		3652020UK4235S	1919	1919	S
0002		3652020UK4235S	1919	1919	S
0002		3652020UK4235S	1919	1919	S
0002		3652020UK4235S	1919	1919	S
<b>CL CORREDERA CRISTO,0040</b>					
0001		3552605UK4235S	1900	1900	S
0002		3552605UK4235S	1900	1900	S
<b>CL CRISTO GUIA,0007</b>					
0000		4152018UK4245S	1972	1972	
<b>CL CRUZ HILO,0009</b>					
0001		2556509UK3225N	1972	1972	
0001		2556509UK3225N	1972	1972	
0002		2556509UK3225N	1972	1972	
0002		2556509UK3225N	1972	1972	
<b>CL CRUZ PINTON,0001</b>					
0001		2752601UK3225S	1972	1972	
0001		2752601UK3225S	1972	1972	
0001		2752601UK3225S	1972	1972	
0001		2752601UK3225S	1972	1972	
0001		2752601UK3225S	1972	1972	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL DELGADILLO,0001</b>					
	0001	3753407UK4235S	1900	1900	S
	0002	3753407UK4235S	1900	1900	S
<b>CL DELGADILLO,0003</b>					
	0001	3753406UK4235S	1946	1946	S
	0001	3753406UK4235S	1946	1946	S
	0002	3753406UK4235S	1946	1946	S
	0002	3753406UK4235S	1946	1946	S
	0003	3753406UK4235S	1946	1946	S
	0003	3753406UK4235S	1946	1946	S
<b>CL DELGADILLO,0005</b>					
	0001	3753405UK4235S	1898	1898	S
	0001	3753405UK4235S	1898	1898	S
	0001	3753405UK4235S	1898	1898	S
<b>CL DELGADILLO,0009</b>					
	0001	3753403UK4235S	1900	1900	S
<b>CL DR MUÑOZ URRRA,0002</b>					
	0002	4254705UK4245S	1940	1940	S
	0003	4254705UK4245S	1940	1940	S
<b>CL EMILIO NIVEIRO ROMO,0003</b>					
	0001	2551019UK4225S	1972	1972	
	0001	2551019UK4225S	1972	1972	
<b>CL EMILIO NIVEIRO ROMO,0005</b>					
	0001	2551018UK4225S	1972	1972	
<b>CL EMILIO NIVEIRO ROMO,0016</b>					
	0001	2651010UK4225S	1972	1972	
	0001	2651010UK4225S	1972	1972	
	0001	2651010UK4225S	1972	1972	
<b>CL EMILIO NIVEIRO ROMO,0019</b>					
	0001	2551012UK4225S	1972	1972	
	0001	2551012UK4225S	1972	1972	
<b>CL EMILIO NIVEIRO ROMO,0020</b>					
	0001	2652716UK4225S	1972	1972	
	0001	2652716UK4225S	1972	1972	
	0001	2652716UK4225S	1972	1972	
<b>CL EMILIO NIVEIRO ROMO,0021</b>					
	0001	2551011UK4225S	1972	1972	
	0001	2551011UK4225S	1972	1972	
<b>CL EMILIO NIVEIRO ROMO,0023</b>					
	0001	2551010UK4225S	1972	1972	
<b>CL EMILIO NIVEIRO ROMO,0025</b>					
	0001	2551009UK4225S	1972	1972	
	0001	2551009UK4225S	1972	1972	
<b>CL EMILIO NIVEIRO ROMO,0026</b>					
	0001	2652706UK4225S	1972	1972	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL EMILIO NIVEIRO ROMO,0033</b>					
	0001	2551007UK4225S	1972	1972	
	0001	2551007UK4225S	1972	1972	
<b>CL EMILIO NIVEIRO ROMO,0049</b>					
	0001	2453001UK4225S	1972	1972	
<b>CL EUSEBIO RUBALCABA,0010</b>					
	0000	4560804UK4246S	1972	1972	
<b>CL EUSEBIO RUBALCABA,0012</b>					
	0000	4560803UK4246S	1972	1972	
<b>CL FERNANDO ROJAS,0003</b>					
	0001	3352002UK4235S	1900	1900	S
	0001	3352002UK4235S	1900	1900	S
	0001	3352002UK4235S	1900	1900	S
	0001	3352002UK4235S	1900	1900	S
	0001	3352002UK4235S	1900	1900	S
	0001	3352002UK4235S	1900	1900	S
	0002	3352002UK4235S	1900	1900	S
	0002	3352002UK4235S	1900	1900	S
	0002	3352002UK4235S	1900	1900	S
	0002	3352002UK4235S	1900	1900	S
	0002	3352002UK4235S	1900	1900	S
	0002	3352002UK4235S	1900	1900	S
	0003	3352002UK4235S	1900	1900	S
	0003	3352002UK4235S	1900	1900	S
	0003	3352002UK4235S	1900	1900	S
	0003	3352002UK4235S	1900	1900	S
	0003	3352002UK4235S	1900	1900	S
	0003	3352002UK4235S	1900	1900	S
<b>CL FRAY HDO TALAVERA,0007</b>					
	0001	3553606UK4235S	1972	1972	
<b>CL FRAY HDO TALAVERA,0011</b>					
	0001	3553605UK4235S	1892	1892	S
	0001	3553605UK4235S	1892	1892	S
<b>CL FRESNO,0003</b>					
	0001	3541004UK4234S	1972	1972	
	0001	3541004UK4234S	1972	1972	
	0002	3541004UK4234S	1972	1972	
	0002	3541004UK4234S	1972	1972	
<b>CL FRESNO,0005</b>					
	0001	3541003UK4234S	1972	1972	
	0002	3541003UK4234S	1972	1972	
<b>CL FRESNO,0012</b>					
	0001	3440007UK4234S	1972	1972	
	0001	3440007UK4234S	1972	1972	
	0002	3440007UK4234S	1972	1972	
	0002	3440007UK4234S	1972	1972	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL FRESNO,0013</b>					
	0001	3440306UK4234S	1972	1972	
	0002	3440306UK4234S	1972	1972	
<b>CL FRESNO,0016</b>					
	0001	3440008UK4234S	1972	1972	
	0001	3440008UK4234S	1972	1972	
	0002	3440008UK4234S	1972	1972	
	0002	3440008UK4234S	1972	1972	
	0003	3440008UK4234S	1972	1972	
	0003	3440008UK4234S	1972	1972	
	0004	3440008UK4234S	1972	1972	
	0004	3440008UK4234S	1972	1972	
<b>CL FRESNO,0017</b>					
	0001	3439201UK4233N	1972	1972	
	0001	3439201UK4233N	1972	1972	
	0002	3439201UK4233N	1972	1972	
	0002	3439201UK4233N	1972	1972	
	0003	3439201UK4233N	1972	1972	
	0003	3439201UK4233N	1972	1972	
<b>CL FRESNO,0021</b>					
	0001	3439209UK4233N	1972	1972	
	0001	3439209UK4233N	1972	1972	
	0002	3439209UK4233N	1972	1972	
	0002	3439209UK4233N	1972	1972	
<b>CL FRESNO,0023</b>					
	0001	3439208UK4233N	1972	1972	
	0001	3439208UK4233N	1972	1972	
	0002	3439208UK4233N	1972	1972	
	0002	3439208UK4233N	1972	1972	
<b>CL FRESNO,0025</b>					
	0001	3439207UK4233N	1972	1972	
	0002	3439207UK4233N	1972	1972	
<b>CL GABRIEL ALONSO HERRERA,0004</b>					
	0001	3650004UK4235S	1900	1900	S
<b>CL GABRIEL ALONSO HERRERA,0008</b>					
	0001	3649203UK4234N	1892	1892	S
	0002	3649203UK4234N	1892	1892	S
<b>CL GABRIEL ALONSO HERRERA,0019</b>					
	0001	3750024UK4235S	1900	1900	S
	0001	3750024UK4235S	1900	1900	S
<b>CL GASPAR DUQUE,0004</b>					
	0001	3651106UK4235S	1900	1900	S
	0002	3651106UK4235S	1900	1900	S
	0003	3651106UK4235S	1900	1900	S
<b>CL GASPAR DUQUE,0006</b>					
	0001	3651107UK4235S	1900	1900	S

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL GASPAR DUQUE,0009</b>					
	0000	3651508UK4235S	1972	1972	
<b>CL GASPAR DUQUE,0010</b>					
	0001	3651109UK4235S	1900	1900	S
	0002	3651109UK4235S	1900	1900	S
<b>CL GASPAR DUQUE,0012</b>					
	0001	3651110UK4235S	1900	1900	S
	0001	3651110UK4235S	1900	1900	S
<b>CL GASPAR DUQUE,0014</b>					
	0001	3651111UK4235S	2000	2000	S
	0001	3651111UK4235S	2000	2000	S
	0002	3651111UK4235S	2000	2000	S
	0002	3651111UK4235S	2000	2000	S
<b>CL GASPAR DUQUE,0016</b>					
	0001	3651112UK4235S	1900	1900	S
	0001	3651112UK4235S	1900	1900	S
<b>CL GL CUESTA,0007</b>					
	0000	4260714UK4246S	1972	1972	
<b>CL GORGOÑA,0002</b>					
	0001	2955201UK3225N	1900	1900	S
<b>CL HERRERIAS,0004</b>					
	0001	3449002UK4234N	1900	1900	S
	0002	3449002UK4234N	1900	1900	S
	0003	3449002UK4234N	1900	1900	S
	0004	3449002UK4234N	1900	1900	S
<b>CL HORNO RIO,0001</b>					
	0001	3849314UK4234N	1900	1900	S
<b>CL HORNO RIO,0002</b>					
	0001	3849402UK4234N	1982	1982	S
	0001	3849402UK4234N	1982	1982	S
<b>CL HORNO RIO,0003</b>					
	0001	3849313UK4234N	1900	1900	S
<b>CL HORNO RIO,0005</b>					
	0001	3849312UK4234N	1900	1900	S
	0001	3849312UK4234N	1900	1900	S
<b>CL HOSPITAL,0003</b>					
	0001	3653112UK4235S	1900	1900	S
	0002	3653112UK4235S	1900	1900	S
<b>CL HOSPITAL,0007</b>					
	0000	3653111UK4235S	1900	1900	S
<b>CL HUERTA SAN AGUSTIN,0000</b>					
	0001	3949002UK4234N	1900	1900	
<b>CL HUERTA SAN AGUSTIN,0020</b>					
	0001	3849308UK4234N	1900	1900	S

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL HUERTA SAN AGUSTIN,0024</b>					
	0001	3849309UK4234N	1900	1900	S
	0001	3849309UK4234N	1900	1900	S
<b>CL HUERTA SAN AGUSTIN,0026</b>					
	0001	3849310UK4234N	1900	1900	S
	0001	3849310UK4234N	1900	1900	S
	0001	3849310UK4234N	1900	1900	S
	0002	3849310UK4234N	1900	1900	S
	0002	3849310UK4234N	1900	1900	S
	0002	3849310UK4234N	1900	1900	S
<b>CL HUERTA SAN AGUSTIN,0028</b>					
	0001	3849311UK4234N	1900	1900	S
	0001	3849311UK4234N	1900	1900	S
<b>CL HUERTA SAN AGUSTIN,0035</b>					
	0001	3849607UK4234N	1900	1900	S
<b>CL IGLESIA,0010</b>					
	0001	3056H020035918	1972	1972	
	0001	3056H020035918	1972	1972	
	0001	3056H020035918	1972	1972	
	0002	3056H020035918	1972	1972	
	0002	3056H020035918	1972	1972	
	0002	3056H020035918	1972	1972	
	0003	3056H020035918	1972	1972	
	0003	3056H020035918	1972	1972	
	0003	3056H020035918	1972	1972	
	0004	3056H020035918	1972	1972	
	0004	3056H020035918	1972	1972	
	0004	3056H020035918	1972	1972	
<b>CL ILDEFONSO SANCHEZ,0003</b>					
	0000	3558508UK4235N	1967	1967	
<b>CL ISAAC GABALDON,0005</b>					
	0000	4259802UK4245N	1967	1967	
<b>CL JACINTO AGUIRRE,0008</b>					
	0000	4655011UK4245N	1955	1955	S
<b>CL JACINTO AGUIRRE,0010</b>					
	0000	4655012UK4245N	1955	1955	S
<b>CL JOAQUINA SANTANDER,0029</b>					
	0000	4655610UK4245N	1967	1967	
<b>CL JOAQUINA SANTANDER,0032</b>					
	0001	4554001UK4245S	1960	1960	
<b>CL JUAN RUIZ LUNA,0016</b>					
	0000	4455011UK4245N	1955	1955	S
<b>CL JUAN RUIZ LUNA,0018</b>					
	0000	4455012UK4245N	1955	1955	S
<b>CL LUIS JIMENEZ,0001</b>					

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0001	3451006UK4235S	1900	1900	S
	0002	3451006UK4235S	1900	1900	S
	0003	3451006UK4235S	1900	1900	S
<b>CL LUIS JIMENEZ,0007</b>					
	0000	3451004UK4235S	1967	1967	
<b>CL LUIS JIMENEZ,0011</b>					
	0001	3451002UK4235S	1900	1900	S
<b>CL MARQUES MIRASOL,0021</b>					
	0000	3554006UK4235S	1972	1972	
<b>CL MARQUESITAS,0005</b>					
	0001	3553622UK4235S	1972	1972	
	0002	3553622UK4235S	1972	1972	
	0003	3553622UK4235S	1972	1972	
<b>CL MARRUPE,0021</b>					
	0000	3659002UK4235N	1967	1967	
<b>CL MATAS,0004</b>					
	0001	3439002UK4233N	1972	1972	
	0001	3439002UK4233N	1972	1972	
	0001	3439002UK4233N	1972	1972	
	0001	3439002UK4233N	1972	1972	
<b>CL MATAS,0006</b>					
	0001	3439003UK4233N	1972	1972	
	0001	3439003UK4233N	1972	1972	
	0001	3439003UK4233N	1972	1972	
	0001	3439003UK4233N	1972	1972	
	0001	3439003UK4233N	1972	1972	
	0001	3439003UK4233N	1972	1972	
	0001	3439003UK4233N	1972	1972	
	0001	3439003UK4233N	1972	1972	
<b>CL MATAS,0008</b>					
	0001	3439004UK4233N	1972	1972	
	0001	3439004UK4233N	1972	1972	
	0001	3439004UK4233N	1972	1972	
	0001	3439004UK4233N	1972	1972	
	0001	3439004UK4233N	1972	1972	
	0002	3439004UK4233N	1972	1972	
	0002	3439004UK4233N	1972	1972	
	0002	3439004UK4233N	1972	1972	
	0002	3439004UK4233N	1972	1972	
	0002	3439004UK4233N	1972	1972	
<b>CL MATAS,0008D</b>					
	0001	3439013UK4233N	1972	1972	
<b>CL MATAS,0010</b>					
	0001	3439005UK4233N	1972	1972	
<b>CL MATAS,0015</b>					
	0001	3439206UK4233N	1972	1972	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0002	3439206UK4233N	1972	1972	
<b>CL MATAS,0017</b>					
	0001	3439205UK4233N	1972	1972	
	0002	3439205UK4233N	1972	1972	
<b>CL MEJORADA,0021</b>					
	0000	3057301UK4235N	1972	1972	
<b>CL MERIDA,0005</b>					
	0001	3549015UK4234N	1936	1936	S
<b>CL MERIDA,0007</b>					
	0001	3549014UK4234N	1936	1936	S
	0002	3549014UK4234N	1936	1936	S
<b>CL MESONES,0002</b>					
	0000	3753413UK4235S	1998	1998	S
<b>CL MESONES,0003</b>					
	0001	3752006UK4235S	1900	1900	S
	0001	3752006UK4235S	1900	1900	S
	0002	3752006UK4235S	1900	1900	S
	0002	3752006UK4235S	1900	1900	S
	0003	3752006UK4235S	1900	1900	S
	0003	3752006UK4235S	1900	1900	S
<b>CL MESONES,0004</b>					
	0001	3753414UK4235S	1900	1900	S
	0001	3753414UK4235S	1900	1900	S
	0001	3753414UK4235S	1900	1900	S
	0002	3753414UK4235S	1900	1900	S
	0002	3753414UK4235S	1900	1900	S
	0002	3753414UK4235S	1900	1900	S
	0003	3753414UK4235S	1900	1900	S
	0003	3753414UK4235S	1900	1900	S
	0003	3753414UK4235S	1900	1900	S
<b>CL MESONES,0006</b>					
	0001	3753415UK4235S	1941	1941	S
	0002	3753415UK4235S	1941	1941	S
	0003	3753415UK4235S	1941	1941	S
	0004	3753415UK4235S	1941	1941	S
	0005	3753415UK4235S	1941	1941	S
	0006	3753415UK4235S	1941	1941	S
	0007	3753415UK4235S	1941	1941	S
<b>CL MESONES,0008</b>					
	0001	3753416UK4235S	1900	1900	S
	0001	3753416UK4235S	1900	1900	S
	0001	3753416UK4235S	1900	1900	S
	0001	3753416UK4235S	1900	1900	S
	0001	3753416UK4235S	1900	1900	S
	0001	3753416UK4235S	1900	1900	S
	0001	3753416UK4235S	1900	1900	S
	0002	3753416UK4235S	1900	1900	S





<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0003	3754801UK4235S	1900	1900	S
	0003	3754801UK4235S	1900	1900	S
<b>CL MESONES,0044</b>					
	0001	3755704UK4235N	1930	1930	S
<b>CL MONTESCLAROS,0001</b>					
	0000	3156314UK4235N	1972	1972	
<b>CL NAVALCAN,0002</b>					
	0001	2752016UK4225S	1972	1972	
	0002	2752016UK4225S	1972	1972	
<b>CL NAVALCAN,0013</b>					
	0000	2651002UK4225S	1972	1972	
<b>CL NAVALCAN,0015</b>					
	0001	2651001UK4225S	1972	1972	
	0001	2651001UK4225S	1972	1972	
	0001	2651001UK4225S	1972	1972	
<b>CL NAVALCAN,0019</b>					
	0001	2652708UK4225S	1972	1972	
	0001	2652708UK4225S	1972	1972	
<b>CL NAVALCAN,0024</b>					
	0001	2752026UK4225S	1972	1972	
	0001	2752026UK4225S	1972	1972	
<b>CL NAVALCAN,0026</b>					
	0001	2752027UK4225S	1972	1972	
	0001	2752027UK4225S	1972	1972	
<b>CL NAVALCAN,0027</b>					
	0001	2652704UK4225S	1972	1972	
<b>CL NAVALCAN,0028</b>					
	0001	2752028UK4225S	1972	1972	
	0001	2752028UK4225S	1972	1972	
<b>CL NAVALCAN,0029</b>					
	0001	2652703UK4225S	1972	1972	
	0001	2652703UK4225S	1972	1972	
<b>CL NAVALCAN,0031</b>					
	0001	2652702UK4225S	1972	1972	
<b>CL NAVALCAN,0033</b>					
	0001	2652701UK4225S	1972	1972	
	0001	2652701UK4225S	1972	1972	
	0001	2652701UK4225S	1972	1972	
	0001	2652701UK4225S	1972	1972	
<b>CL NAVALCAN,0050</b>					
	0000	2752041UK4225S	1972	1972	
<b>CL NAVALCAN,0052</b>					
	0001	2752042UK4225S	1972	1972	
	0001	2752042UK4225S	1972	1972	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL NAVALCAN,0060</b>					
	0001	2752046UK4225S	1972	1972	
<b>CL NIEVES,0022</b>					
	0001	2949026UK4224N	1967	1967	
	0001	2949026UK4224N	1967	1967	
	0001	2949026UK4224N	1967	1967	
<b>CL NORTE,0010</b>					
	0001	2956008UK4225N	1972	1972	
	0001	2956008UK4225N	1972	1972	
	0002	2956008UK4225N	1972	1972	
	0002	2956008UK4225N	1972	1972	
<b>CL OLIVARES,0003</b>					
	0000	3149019UK4234N	1972	1972	
<b>CL ORO,0011</b>					
	0001	4051107UK4245S	1972	1972	
	0002	4051107UK4245S	1972	1972	
<b>CL PADRE J MARIANA,0001</b>					
	0000	3150003UK4235S	1967	1967	
<b>CL PADRE J MARIANA,0002</b>					
	0001	3151015UK4235S	1960	1960	S
	0001	3151015UK4235S	1960	1960	S
	0002	3151015UK4235S	1960	1960	S
	0002	3151015UK4235S	1960	1960	S
	0003	3151015UK4235S	1960	1960	S
	0003	3151015UK4235S	1960	1960	S
<b>CL PADRE J MARIANA,0014</b>					
	0001	3050011UK4235S	1900	1900	S
	0002	3050011UK4235S	1900	1900	S
<b>CL PADRE SALMERON,0003</b>					
	0000	3251028UK4235S	2010	2010	S
<b>CL PADRE SALMERON,0004</b>					
	0001	3252032UK4235S	1910	1910	S
	0001	3252032UK4235S	1910	1910	S
<b>CL PADRE SALMERON,0006</b>					
	0000	3252054UK4235S	2007	2007	S
<b>CL PADRE SALMERON,0012</b>					
	0001	3252035UK4235S	1910	1910	S
	0002	3252035UK4235S	1910	1910	S
<b>CL PADRE SALMERON,0032</b>					
	0000	3151809UK4235S	1972	1972	
<b>CL PALENQUE,0002</b>					
	0001	3550001UK4235S	1955	1955	
	0002	3550001UK4235S	1955	1955	
	0003	3550001UK4235S	1955	1955	
<b>CL PALENQUE,0004</b>					

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0001	3550002UK4235S	1940	1940	S
	0002	3550002UK4235S	1940	1940	S
	0003	3550002UK4235S	1940	1940	S
	0004	3550002UK4235S	1940	1940	S
<b>CL PANADEROS,0048</b>					
	0001	2347026UK4224N	1972	1972	
	0002	2347026UK4224N	1972	1972	
<b>CL PAREDON,0002</b>					
	0001	3440001UK4234S	1972	1972	
	0002	3440001UK4234S	1972	1972	
<b>CL PAREDON,0012</b>					
	0001	3340202UK4234S	1972	1972	
	0001	3340202UK4234S	1972	1972	
<b>CL PAREDON,0012D</b>					
	0001	3340201UK4234S	1972	1972	
<b>CL PAREDON,0016</b>					
	0001	3340204UK4234S	1972	1972	
<b>CL PAREDON,0018</b>					
	0001	3340205UK4234S	1972	1972	
	0001	3340205UK4234S	1972	1972	
<b>CL PAREDON,0037</b>					
	0001	3440013UK4234S	1972	1972	
	0002	3440013UK4234S	1972	1972	
<b>CL PAREDON,0039</b>					
	0001	3440011UK4234S	1972	1972	
	0001	3440011UK4234S	1972	1972	
	0001	3440011UK4234S	1972	1972	
	0002	3440011UK4234S	1972	1972	
	0002	3440011UK4234S	1972	1972	
	0002	3440011UK4234S	1972	1972	
	0003	3440011UK4234S	1972	1972	
	0003	3440011UK4234S	1972	1972	
	0003	3440011UK4234S	1972	1972	
<b>CL PAREDON,0055</b>					
	0001	3439012UK4233N	1972	1972	
	0001	3439012UK4233N	1972	1972	
	0002	3439012UK4233N	1972	1972	
	0002	3439012UK4233N	1972	1972	
<b>CL PAREDON,0061</b>					
	0001	3438010UK4233N	1972	1972	
	0001	3438010UK4233N	1972	1972	
<b>CL PAREDON,0063</b>					
	0001	3438012UK4233N	1972	1972	
<b>CL PARRILLAS,0002</b>					
	0001	2652710UK4225S	1972	1972	
	0002	2652710UK4225S	1972	1972	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL PARRILLAS,0008</b>					
	0001	2652713UK4225S	1972	1972	
<b>CL PARRILLAS,0010</b>					
	0001	2652714UK4225S	1972	1972	
<b>CL PERDON,0001</b>					
	0001	3552604UK4235S	1900	1900	S
	0002	3552604UK4235S	1900	1900	S
<b>CL PIELAGO,0012</b>					
	0000	4360612UK4246S	1967	1967	
<b>CL PILAR,0009</b>					
	0000	4360616UK4246S	1967	1967	
<b>CL PILAR,0023</b>					
	0000	4360604UK4246S	1972	1972	
<b>CL PILAR,0033</b>					
	0000	4460101UK4246S	1972	1972	
<b>CL POETA RAFAEL MORALES,0006</b>					
	0000	3352012UK4235S	1967	1967	
<b>CL PORTIÑA DE SAN MIGUEL,0009</b>					
	0001	3453022UK4235S	1900	1900	S
	0002	3453022UK4235S	1900	1900	S
<b>CL PORTIÑA DE SAN MIGUEL,0019</b>					
	0000	3453017UK4235S	1972	1972	
<b>CL PORTIÑA DE SAN MIGUEL,0032</b>					
	0000	3353815UK4235S	1967	1967	
<b>CL PORTIÑA DE SAN MIGUEL,0054</b>					
	0001	3251001UK4235S	1920	1920	S
	0002	3251001UK4235S	1920	1920	S
<b>CL PORTIÑA DE SAN MIGUEL,0062</b>					
	0001	3251004UK4235S	1900	1900	S
	0001	3251004UK4235S	1900	1900	S
	0002	3251004UK4235S	1900	1900	S
	0002	3251004UK4235S	1900	1900	S
<b>CL PORTIÑA DEL SALVADOR,0030</b>					
	0000	3250018UK4235S	1972	1972	
<b>CL PRADO,0011</b>					
	0000	4054503UK4245S	1972	1972	
<b>CL PUENTE NUEVO,0004</b>					
	0001	3555208UK4235N	1940	1940	S
	0002	3555208UK4235N	1940	1940	S
	0003	3555208UK4235N	1940	1940	S
<b>CL PUERTA RIO TAJO,0001</b>					
	0001	3849317UK4234N	1900	1900	S
	0001	3849317UK4234N	1900	1900	S
	0002	3849317UK4234N	1900	1900	S

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0002	3849317UK4234N	1900	1900	S
<b>CL PUERTA RIO TAJO,0003</b>					
	0001	3849316UK4234N	1900	1900	S
<b>CL PUERTA RIO TAJO,0005</b>					
	0001	3849315UK4234N	1900	1900	S
	0001	3849315UK4234N	1900	1900	S
<b>CL PUERTA RIO TAJO,0007</b>					
	0001	3849401UK4234N	1900	1900	S
<b>CL PUERTA RIO TAJO,0009</b>					
	0001	3849403UK4234N	1900	1900	S
<b>CL QUEMADEROS,0004</b>					
	0001	3440002UK4234S	1972	1972	
	0002	3440002UK4234S	1972	1972	
<b>CL QUEMADEROS,0008</b>					
	0001	3440003UK4234S	1972	1972	
	0001	3440003UK4234S	1972	1972	
	0002	3440003UK4234S	1972	1972	
	0002	3440003UK4234S	1972	1972	
<b>CL QUEMADEROS,0010</b>					
	0001	3440004UK4234S	1972	1972	
	0002	3440004UK4234S	1972	1972	
<b>CL QUEMADEROS,0012</b>					
	0001	3440005UK4234S	1972	1972	
	0002	3440005UK4234S	1972	1972	
<b>CL QUEMADEROS,0014</b>					
	0001	3440006UK4234S	1972	1972	
	0002	3440006UK4234S	1972	1972	
<b>CL QUEMADEROS,0018</b>					
	0001	3440302UK4234S	1972	1972	
	0002	3440302UK4234S	1972	1972	
<b>CL QUEMADEROS,0020</b>					
	0001	3440303UK4234S	1972	1972	
<b>CL RAMON CORROCHANO,0015</b>					
	0000	3759504UK4235N	1972	1972	
<b>CL RAMON Y CAJAL,0003</b>					
	0001	3753005UK4235S	1960	1960	S
	0001	3753005UK4235S	1960	1960	S
	0001	3753005UK4235S	1960	1960	S
	0002	3753005UK4235S	1960	1960	S
	0002	3753005UK4235S	1960	1960	S
	0002	3753005UK4235S	1960	1960	S
<b>CL RAMON Y CAJAL,0005</b>					
	0001	3753004UK4235S	1900	1900	S
	0002	3753004UK4235S	1900	1900	S
	0003	3753004UK4235S	1900	1900	S

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL RAMON Y CAJAL,0018</b>					
	0001	3853015UK4235S	1885	1885	S
<b>CL RECINTO BLANCA ARAGON,0001</b>					
	0000	3956020UK4235N	1972	1972	
<b>CL RIBERA,0001</b>					
	0001	3440012UK4234S	1972	1972	
	0002	3440012UK4234S	1972	1972	
	0003	3440012UK4234S	1972	1972	
<b>CL RIBERA,0006</b>					
	0001	3439103UK4233N	1972	1972	
	0001	3439103UK4233N	1972	1972	
	0002	3439103UK4233N	1972	1972	
	0002	3439103UK4233N	1972	1972	
<b>CL RIBERA,0007</b>					
	0001	3440010UK4234S	1972	1972	
	0001	3440010UK4234S	1972	1972	
	0002	3440010UK4234S	1972	1972	
	0002	3440010UK4234S	1972	1972	
	0003	3440010UK4234S	1972	1972	
	0003	3440010UK4234S	1972	1972	
<b>CL RIBERA,0009</b>					
	0001	3440009UK4234S	1972	1972	
	0001	3440009UK4234S	1972	1972	
	0001	3440009UK4234S	1972	1972	
	0001	3440009UK4234S	1972	1972	
	0002	3440009UK4234S	1972	1972	
	0002	3440009UK4234S	1972	1972	
	0002	3440009UK4234S	1972	1972	
	0002	3440009UK4234S	1972	1972	
	0003	3440009UK4234S	1972	1972	
	0003	3440009UK4234S	1972	1972	
	0003	3440009UK4234S	1972	1972	
	0003	3440009UK4234S	1972	1972	
<b>CL RIBERA,0019</b>					
	0001	3440304UK4234S	1972	1972	
	0001	3440304UK4234S	1972	1972	
	0002	3440304UK4234S	1972	1972	
	0002	3440304UK4234S	1972	1972	
<b>CL RIO TAJO,0002</b>					
	0000	37490010040104	1900	1900	S
<b>CL RIO TAJO,0003</b>					
	0001	3750023UK4235S	1920	1920	S
	0001	3750023UK4235S	1920	1920	S
	0001	3750023UK4235S	1920	1920	S
	0001	3750023UK4235S	1920	1920	S
<b>CL RIO TAJO,0005</b>					
	0001	3750022UK4235S	1900	1900	S

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0001	3750022UK4235S	1900	1900	S
	0001	3750022UK4235S	1900	1900	S
	0001	3750022UK4235S	1900	1900	S
	0001	3750022UK4235S	1900	1900	S
	0002	3750022UK4235S	1900	1900	S
	0002	3750022UK4235S	1900	1900	S
	0002	3750022UK4235S	1900	1900	S
	0002	3750022UK4235S	1900	1900	S
	0002	3750022UK4235S	1900	1900	S
<b>CL RIO TAJO,0007</b>					
	0001	3750021UK4235S	1900	1900	S
	0001	3750021UK4235S	1900	1900	S
	0002	3750021UK4235S	1900	1900	S
	0002	3750021UK4235S	1900	1900	S
<b>CL RIO TAJO,0009</b>					
	0001	3750020UK4235S	1900	1900	S
	0001	3750020UK4235S	1900	1900	S
<b>CL RIO TAJO,0011</b>					
	0001	3750019UK4235S	1900	1900	S
	0002	3750019UK4235S	1900	1900	S
<b>CL RIO TAJO,0013</b>					
	0001	3750018UK4235S	1900	1900	S
	0001	3750018UK4235S	1900	1900	S
	0002	3750018UK4235S	1900	1900	S
	0002	3750018UK4235S	1900	1900	S
<b>CL RIO TAJO,0015</b>					
	0001	3750017UK4235S	1900	1900	S
<b>CL RIO TAJO,0025</b>					
	0000	3850007UK4235S	1967	1967	
<b>CL RONDA CAÑILLO,0013</b>					
	0001	3749008UK4234N	1900	1900	S
<b>CL RONDA CAÑILLO,0016</b>					
	0001	3749005UK4234N	1900	1900	S
	0002	3749005UK4234N	1900	1900	S
<b>CL SAN AGUSTIN VIEJO,0003</b>					
	0001	3851015UK4235S	1900	1900	S
	0001	3851015UK4235S	1900	1900	S
	0002	3851015UK4235S	1900	1900	S
	0002	3851015UK4235S	1900	1900	S
<b>CL SAN AGUSTIN VIEJO,0004</b>					
	0000	3850002UK4235S	1900	1900	S
<b>CL SAN AGUSTIN VIEJO,0007</b>					
	0001	3851014UK4235S	1900	1900	S
<b>CL SAN AGUSTIN VIEJO,0011</b>					
	0001	3851012UK4235S	1900	1900	S
	0001	3851012UK4235S	1900	1900	S



<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL SAN AGUSTIN VIEJO,0013</b>					
	0001	3851011UK4235S	1900	1900	S
	0001	3851011UK4235S	1900	1900	S
<b>CL SAN AGUSTIN VIEJO,0014</b>					
	0001	3849702UK4234N	1900	1900	S
	0001	3849702UK4234N	1900	1900	S
	0001	3849702UK4234N	1900	1900	S
	0002	3849702UK4234N	1900	1900	S
	0002	3849702UK4234N	1900	1900	S
	0002	3849702UK4234N	1900	1900	S
<b>CL SAN AGUSTIN VIEJO,0015</b>					
	0000	3849322UK4234N	1900	1900	S
<b>CL SAN AGUSTIN VIEJO,0027</b>					
	0001	3849318UK4234N	1900	1900	S
<b>CL SAN AGUSTIN VIEJO,0037</b>					
	0001	3849606UK4234N	1900	1900	S
<b>CL SAN ANTONIO,0059</b>					
	0001	1644013UK4214S	1972	1972	
	0001	1644013UK4214S	1972	1972	
	0002	1644013UK4214S	1972	1972	
	0002	1644013UK4214S	1972	1972	
	0003	1644013UK4214S	1972	1972	
	0003	1644013UK4214S	1972	1972	
<b>CL SAN ANTON,0003</b>					
	0000	3150034UK4235S	1972	1972	
<b>CL SAN BENITO,0005</b>					
	0001	3549019UK4234N	1980	1980	S
	0002	3549019UK4234N	1980	1980	S
<b>CL SAN BENITO,0007</b>					
	0001	3549018UK4234N	1955	1955	S
<b>CL SAN BENITO,0009</b>					
	0001	3549017UK4234N	1936	1936	S
	0001	3549017UK4234N	1936	1936	S
<b>CL SAN BENITO,0011</b>					
	0001	3549016UK4234N	1936	1936	S
	0001	3549016UK4234N	1936	1936	S
<b>CL SAN BERNARDO,0001</b>					
	0001	3850001UK4235S	1900	1900	S
	0002	3850001UK4235S	1900	1900	S
<b>CL SAN BERNARDO,0004</b>					
	0001	3750010UK4235S	1900	1900	S
	0001	3750010UK4235S	1900	1900	S
<b>CL SAN BERNARDO,0006</b>					
	0001	3750011UK4235S	1856	1856	S
	0001	3750011UK4235S	1856	1856	S

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL SAN BERNARDO,0008</b>					
	0001	3750012UK4235S	2001	2001	S
	0001	3750012UK4235S	2001	2001	S
<b>CL SAN BERNARDO,0012</b>					
	0001	3750013UK4235S	2007	2007	S
	0001	3750013UK4235S	2007	2007	S
<b>CL SAN BERNARDO,0018</b>					
	0001	3750016UK4235S	1900	1900	S
	0001	3750016UK4235S	1900	1900	S
<b>CL SAN CRISTOBAL,0006</b>					
	0001	1743505UK4214S	1972	1972	
	0002	1743505UK4214S	1972	1972	
	0003	1743505UK4214S	1972	1972	
<b>CL SAN CRISTOBAL,0016</b>					
	0001	1743510UK4214S	1972	1972	
	0001	1743510UK4214S	1972	1972	
	0001	1743510UK4214S	1972	1972	
	0001	1743510UK4214S	1972	1972	
	0001	1743510UK4214S	1972	1972	
	0002	1743510UK4214S	1972	1972	
	0002	1743510UK4214S	1972	1972	
	0002	1743510UK4214S	1972	1972	
	0002	1743510UK4214S	1972	1972	
	0002	1743510UK4214S	1972	1972	
<b>CL SAN CRISTOBAL,0024</b>					
	0001	1642802UK4214S	1972	1972	
	0002	1642802UK4214S	1972	1972	
<b>CL SAN DAMASO,0017</b>					
	0001	1843002UK4214S	1972	1972	
<b>CL SAN FRANCISCO,0001</b>					
	0001	3753412UK4235S	1960	1960	S
	0002	3753412UK4235S	1960	1960	S
<b>CL SAN FRANCISCO,0003</b>					
	0001	3753411UK4235S	1960	1960	S
	0001	3753411UK4235S	1960	1960	S
	0001	3753411UK4235S	1960	1960	S
	0002	3753411UK4235S	1960	1960	S
	0002	3753411UK4235S	1960	1960	S
	0002	3753411UK4235S	1960	1960	S
	0003	3753411UK4235S	1960	1960	S
	0003	3753411UK4235S	1960	1960	S
	0003	3753411UK4235S	1960	1960	S
<b>CL SAN FRANCISCO,0008</b>					
	0001	3852009UK4235S	1940	1940	S
	0001	3852009UK4235S	1940	1940	S
	0002	3852009UK4235S	1940	1940	S
	0002	3852009UK4235S	1940	1940	S

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0003	3852009UK4235S	1940	1940	S
	0003	3852009UK4235S	1940	1940	S
<b>CL SAN FRANCISCO,0009</b>					
	0001	3753409UK4235S	1900	1900	S
	0001	3753409UK4235S	1900	1900	S
	0001	3753409UK4235S	1900	1900	S
<b>CL SAN FRANCISCO,0012</b>					
	0001	3852011UK4235S	1918	1918	S
<b>CL SAN FRANCISCO,0013</b>					
	0001	3853011UK4235S	1900	1900	S
	0002	3853011UK4235S	1900	1900	S
	0003	3853011UK4235S	1900	1900	S
<b>CL SAN FRANCISCO,0016</b>					
	0001	3852001UK4235S	1960	1960	S
	0001	3852001UK4235S	1960	1960	S
	0001	3852001UK4235S	1960	1960	S
	0002	3852001UK4235S	1960	1960	S
	0002	3852001UK4235S	1960	1960	S
	0002	3852001UK4235S	1960	1960	S
	0003	3852001UK4235S	1960	1960	S
	0003	3852001UK4235S	1960	1960	S
	0003	3852001UK4235S	1960	1960	S
<b>CL SAN FRANCISCO,0018</b>					
	0001	3852209UK4235S	1900	1900	S
	0001	3852209UK4235S	1900	1900	S
	0002	3852209UK4235S	1900	1900	S
	0002	3852209UK4235S	1900	1900	S
<b>CL SAN FRANCISCO,0019</b>					
	0001	3853008UK4235S	1900	1900	S
	0001	3853008UK4235S	1900	1900	S
	0002	3853008UK4235S	1900	1900	S
	0002	3853008UK4235S	1900	1900	S
	0003	3853008UK4235S	1900	1900	S
	0003	3853008UK4235S	1900	1900	S
<b>CL SAN FRANCISCO,0023</b>					
	0001	3853006UK4235S	2005	2005	S
	0001	3853006UK4235S	2005	2005	S
	0003	3853006UK4235S	2005	2005	S
	0003	3853006UK4235S	2005	2005	S
<b>CL SAN FRANCISCO,0024</b>					
	0000	3852212UK4235S	1900	1900	S
<b>CL SAN FRANCISCO,0025</b>					
	0001	3853005UK4235S	1900	1900	S
	0001	3853005UK4235S	1900	1900	S
	0001	3853005UK4235S	1900	1900	S
<b>CL SAN FRANCISCO,0027</b>					
	0001	3853004UK4235S	1900	1900	S

<b>SITUACIÓN</b>				
<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
0001	3853004UK4235S	1900	1900	S
0002	3853004UK4235S	1900	1900	S
0002	3853004UK4235S	1900	1900	S
<b>CL SAN FRANCISCO,0027D</b>				
0001	3853003UK4235S	1900	1900	S
0001	3853003UK4235S	1900	1900	S
<b>CL SAN GERVASIO,0003</b>				
0001	1543019UK4214S	1967	1967	
<b>CL SAN GERVASIO,0007</b>				
0001	1543017UK4214S	1967	1967	
0002	1543017UK4214S	1967	1967	
<b>CL SAN HILARIO,0009</b>				
0001	1743519UK4214S	1972	1972	
0002	1743519UK4214S	1972	1972	
0003	1743519UK4214S	1972	1972	
<b>CL SAN HILARIO,0013</b>				
0001	1743509UK4214S	1972	1972	
0001	1743509UK4214S	1972	1972	
0001	1743509UK4214S	1972	1972	
0002	1743509UK4214S	1972	1972	
0002	1743509UK4214S	1972	1972	
0002	1743509UK4214S	1972	1972	
0003	1743509UK4214S	1972	1972	
0003	1743509UK4214S	1972	1972	
0003	1743509UK4214S	1972	1972	
0004	1743509UK4214S	1972	1972	
0004	1743509UK4214S	1972	1972	
0004	1743509UK4214S	1972	1972	
<b>CL SAN HILARIO,0015</b>				
0001	1743517UK4214S	1972	1972	
0002	1743517UK4214S	1972	1972	
<b>CL SAN HILARIO,0017</b>				
0002	1743516UK4214S	1972	1972	
<b>CL SAN JAVIER,0007</b>				
0001	1443029UK4214S	1972	1972	
0001	1443029UK4214S	1972	1972	
<b>CL SAN JOAQUIN,0020</b>				
0001	2043706UK4224S	1972	1972	
0002	2043706UK4224S	1972	1972	
0003	2043706UK4224S	1972	1972	
<b>CL SAN JUAN B LA SALLE,0007</b>				
0000	3860003UK4236S	1972	1972	
<b>CL SAN JUAN BOSCO,0004</b>				
0000	2850206UK4225S	1972	1972	
<b>CL SAN JUAN DIOS,0033</b>				
0000	3254004UK4235S	1967	1967	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL SAN MARCOS,0076</b>					
	0000	1742802UK4214S	1972	1972	
<b>CL SAN MARCOS,0080</b>					
	0000	1742804UK4214S	1972	1972	
<b>CL SAN MARCOS,0094</b>					
	0001	1642006UK4214S	1972	1972	
	0001	1642006UK4214S	1972	1972	
	0002	1642006UK4214S	1972	1972	
	0002	1642006UK4214S	1972	1972	
	0003	1642006UK4214S	1972	1972	
	0003	1642006UK4214S	1972	1972	
<b>CL SAN MARCOS,0096</b>					
	0001	1642007UK4214S	1972	1972	
	0001	1642007UK4214S	1972	1972	
<b>CL SAN MARCOS,0100</b>					
	0001	1642009UK4214S	1972	1972	
	0002	1642009UK4214S	1972	1972	
<b>CL SAN MARCOS,0104</b>					
	0001	1543020UK4214S	1967	1967	
	0001	1543020UK4214S	1967	1967	
	0002	1543020UK4214S	1967	1967	
	0002	1543020UK4214S	1967	1967	
<b>CL SAN PEDRO ALCANTA,0006</b>					
	0000	3858316UK4235N	1972	1972	
<b>CL SAN RAMIRO,0007</b>					
	0001	1443023UK4214S	1967	1967	
	0001	1443023UK4214S	1967	1967	
<b>CL SAN RUFINO,0008</b>					
	0001	1544003UK4214S	1972	1972	
	0001	1544003UK4214S	1972	1972	
	0002	1544003UK4214S	1972	1972	
	0002	1544003UK4214S	1972	1972	
	0003	1544003UK4214S	1972	1972	
	0003	1544003UK4214S	1972	1972	
<b>CL SAN SEBASTIAN,0005</b>					
	0001	3654008UK4235S	1960	1960	S
	0002	3654008UK4235S	1960	1960	S
<b>CL SAN SEBASTIAN,0009</b>					
	0001	3654006UK4235S	1960	1960	S
	0002	3654006UK4235S	1960	1960	S
<b>CL SAN SEBASTIAN,0010</b>					
	0001	3653117UK4235S	1900	1900	S
	0002	3653117UK4235S	1900	1900	S
<b>CL SAN SEBASTIAN,0012</b>					
	0001	3653118UK4235S	1900	1900	S

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0002	3653118UK4235S	1900	1900	S
<b>CL SAN SEBASTIAN,0013</b>					
	0001	3654005UK4235S	1960	1960	S
	0001	3654005UK4235S	1960	1960	S
	0002	3654005UK4235S	1960	1960	S
	0002	3654005UK4235S	1960	1960	S
<b>CL SAN SEBASTIAN,0014</b>					
	0001	3653119UK4235S	1900	1900	S
	0001	3653119UK4235S	1900	1900	S
	0001	3653119UK4235S	1900	1900	S
<b>CL SAN SEBASTIAN,0016</b>					
	0001	3653120UK4235S	2005	2005	S
<b>CL SAN SEBASTIAN,0022</b>					
	0001	3653121UK4235S	1900	1900	S
	0001	3653121UK4235S	1900	1900	S
<b>CL SAN VALERIANO,0011</b>					
	0001	1944115UK4214S	1967	1967	
	0001	1944115UK4214S	1967	1967	
	0001	1944115UK4214S	1967	1967	
	0001	1944115UK4214S	1967	1967	
	0002	1944115UK4214S	1967	1967	
	0002	1944115UK4214S	1967	1967	
	0002	1944115UK4214S	1967	1967	
	0002	1944115UK4214S	1967	1967	
<b>CL SANTA CRISTETA,0004</b>					
	0000	4059006UK4245N	1972	1972	
<b>CL SANTA CRISTETA,0010</b>					
	0000	4059007UK4245N	1972	1972	
<b>CL SANTA ENGRACIA,0036</b>					
	0002	3928405UK4232N	1960	1960	
<b>CL SANTA EUGENIA,0001</b>					
	0001	3953025UK4235S	1900	1900	S
<b>CL SANTA EUGENIA,0003</b>					
	0001	3953024UK4235S	1900	1900	S
	0002	3953024UK4235S	1900	1900	S
<b>CL SANTA EUGENIA,0004</b>					
	0001	3852202UK4235S	1940	1940	S
<b>CL SANTA EUGENIA,0006</b>					
	0001	3852203UK4235S	1995	1995	S
	0002	3852203UK4235S	1995	1995	S
<b>CL SANTA EUGENIA,0008</b>					
	0002	3852204UK4235S	1900	1900	S
	0003	3852204UK4235S	1900	1900	S
<b>CL SANTA EUGENIA,0009</b>					
	0001	3952010UK4235S	1900	1900	S

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>CL SANTA SABINA,0007</b>					
	0000	3958003UK4235N	1967	1967	
<b>CL SANTA SABINA,0009</b>					
	0000	3958002UK4235N	1972	1972	
<b>CL SANTA TERESA JESUS,0034</b>					
	0000	4056011UK4245N	1967	1967	
<b>CL SANTA TERESA JESUS,0049</b>					
	0001	3958006UK4235N	1975	1975	S
<b>CL SANTA TERESA JESUS,0062</b>					
	0000	4158715UK4245N	1972	1972	
<b>CL SANTA TERESA JESUS,0064</b>					
	0000	4158716UK4245N	1972	1972	
<b>CL SANTO DOMINGO,0014</b>					
	0000	3353827UK4235S	1972	1972	
<b>CL SANTO DOMINGO,0021</b>					
	0000	3154001UK4235S	1930	1930	S
	0000	3154001UK4235S	1960	1960	S
<b>CL SANTO TOMAS,0009</b>					
	0001	1843024UK4214S	1972	1972	
<b>CL SEGURILLA,0027</b>					
	0000	3356006UK4235N	1967	1967	
<b>CL SOLANA,0003</b>					
	0001	3753109UK4235S	1900	1900	S
	0001	3753109UK4235S	1900	1900	S
	0001	3753109UK4235S	1900	1900	S
<b>CL SOLANA,0010</b>					
	0001	3753009UK4235S	1900	1900	S
	0001	3753009UK4235S	1900	1900	S
<b>CL SOL,0016</b>					
	0001	3952502UK4235S	1900	1900	S
<b>CL SOL,0017</b>					
	0001	3952009UK4235S	1900	1900	S
<b>CL SOL,0021</b>					
	0001	3952007UK4235S	1900	1900	S
	0002	3952007UK4235S	1900	1900	S
<b>CL SOL,0030</b>					
	0000	4051111UK4245S	1972	1972	
<b>CL TEATRO,0003</b>					
	0001	3650206UK4235S	1900	1900	S
	0001	3650206UK4235S	1900	1900	S
<b>CL TEATRO,0007</b>					
	0001	3650204UK4235S	1900	1900	S
<b>CL TEATRO,0010</b>					

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0001	3651505UK4235S	1954	1954	S
	0002	3651505UK4235S	1954	1954	S
	0003	3651505UK4235S	1954	1954	S
<b>CL TEATRO,0012</b>					
	0001	3651506UK4235S	1900	1900	S
	0002	3651506UK4235S	1900	1900	S
	0003	3651506UK4235S	1900	1900	S
<b>CL TEMPLARIOS,0041</b>					
	0001	3247011UK4234N	1950	1950	S
	0002	3247011UK4234N	1950	1950	S
<b>CL TEMPLARIOS,0045</b>					
	0001	3247008UK4234N	1965	1965	S
	0002	3247008UK4234N	1965	1965	S
<b>CL TINTE,0003</b>					
	0001	3251026UK4235S	1930	1930	S
	0001	3251026UK4235S	1930	1930	S
<b>CL TINTE,0004</b>					
	0001	3151003UK4235S	1900	1900	S
<b>CL TINTE,0005</b>					
	0001	3251025UK4235S	1900	1900	S
	0001	3251025UK4235S	1900	1900	S
<b>CL TINTE,0006</b>					
	0001	3151004UK4235S	1900	1900	S
	0001	3151004UK4235S	1900	1900	S
	0001	3151004UK4235S	1900	1900	S
<b>CL TINTE,0009</b>					
	0001	3251024UK4235S	1930	1930	S
	0001	3251024UK4235S	1930	1930	S
<b>CL TINTE,0011</b>					
	0001	3251023UK4235S	1936	1936	S
<b>CL TINTE,0015</b>					
	0001	3251022UK4235S	1900	1900	S
<b>CL TINTE,0018</b>					
	0001	3151007UK4235S	1900	1900	S
	0002	3151007UK4235S	1900	1900	S
<b>CL TINTE,0026</b>					
	0000	3151010UK4235S	1900	1900	S
<b>CL TORO ENCOHETADO,0004</b>					
	0001	3649202UK4234N	1890	1890	S
<b>CL TORO ENCOHETADO,0005</b>					
	0000	3650006UK4235S	1958	1958	S
<b>CL V MEDRANO,0017</b>					
	0002	4162021UK4246S	1972	1972	
<b>CL VALENCIA,0006</b>					



<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0000	3551105UK4235S	1972	1972	
<b>CL VENEZUELA,0001</b>					
	0000	4959016UK4245N	1972	1972	
<b>CL VICARIA VIEJA,0003</b>					
	0001	3851022UK4235S	1900	1900	S
	0001	3851022UK4235S	1900	1900	S
<b>CL VICARIA VIEJA,0005</b>					
	0001	3851021UK4235S	1900	1900	S
	0001	3851021UK4235S	1900	1900	S
<b>CL VICARIA VIEJA,0011</b>					
	0001	3851019UK4235S	1900	1900	S
	0002	3851019UK4235S	1900	1900	S
<b>CL VICARIA VIEJA,0013</b>					
	0001	3851020UK4235S	1900	1900	S
<b>CL VICENTE LEYVA,0013</b>					
	0001	2752069UK4225S	1972	1972	
<b>CL ZONA,0020</b>					
	0000	3356010UK4235N	1967	1967	
<b>CL ZONA,0030</b>					
	0000	3156605UK4235N	1972	1972	
<b>CM VIEJO OROPESA,0004</b>					
	0001	0647002UK4204N	1972	1972	
<b>CR ALBERCHE,0011B</b>					
	0001	3051812UK3225S	1972	1972	
	0001	3051812UK3225S	1972	1972	
<b>CR ALBERCHE,0011D</b>					
	0001	3051813UK3225S	1972	1972	
	0002	3051813UK3225S	1972	1972	
<b>CR CALERA Y CHOZAS,0000</b>					
	0001	1235301UK4213N	1972	1972	
<b>CR EXTREMADURA,0121D</b>					
	0001	0948001UK4204N	1945	1945	S
	0002	0948001UK4204N	1945	1945	S
<b>CR EXTREMADURA,0122</b>					
	0001	0949001UK4204N	1943	1943	S
	0002	0949001UK4204N	1943	1943	S
	0003	0949001UK4204N	1943	1943	S
	0004	0949001UK4204N	1943	1943	S
<b>CR MADRID N-V,0004</b>					
	0001	4852001UK4245S	1967	1967	
	0002	4852001UK4245S	1967	1967	
	0003	4852001UK4245S	1967	1967	
<b>CR MADRID N-V,0032</b>					
	0001	5954001UK4255S	1972	1972	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0002	5954001UK4255S	1972	1972	
<b>DS DISEMINADO,0722</b>					
	0001	001300700UK42C	1967	1967	
<b>DS DISEMINADO,0931</b>					
	0001	001200500UK42F	1972	1972	
<b>DS DISEMINADO,1213</b>					
	0001	002500600UK32F	1967	1967	
	0001	002500600UK32F	1967	1967	
<b>PS ESTACION,0022</b>					
	0000	4258012UK4245N	1972	1972	
<b>PS ESTACION,0061</b>					
	0001	4162006UK4246S	1920	1920	S
	0002	4162006UK4246S	1920	1920	S
<b>PS ESTACION,0075</b>					
	0001	4162001UK4246S	1920	1920	S
	0002	4162001UK4246S	1920	1920	S
	0003	4162001UK4246S	1920	1920	S
<b>PS ESTACION,0078</b>					
	0000	4261206UK4246S	1972	1972	
<b>PS PADRE J MARIANA,0007</b>					
	0001	3149044UK4234N	1900	1900	S
	0002	3149044UK4234N	1900	1900	S
	0003	3149044UK4234N	1900	1900	S
<b>PZ ALBA,0012</b>					
	0001	3454023UK4235S	1967	1967	
	0001	3454023UK4235S	1967	1967	
	0001	3454023UK4235S	1967	1967	
<b>PZ ALFEREZ ROJAS,0006</b>					
	0000	4356005UK4245N	1967	1967	
<b>PZ ARAVACA,0001</b>					
	0001	3453503UK4235S	1887	1887	S
	0002	3453503UK4235S	1887	1887	S
<b>PZ CONSTITUCION,0001</b>					
	0001	2755301UK3225S	1900	1900	S
<b>PZ GABRIEL ALONSO HERRERA,0001</b>					
	0001	8425001UK3282N	1956	1956	S
	0002	8425001UK3282N	1956	1956	S
<b>PZ GABRIEL ALONSO HERRERA,0010</b>					
	0001	8626009UK3282N	1956	1956	S
<b>PZ IGLESIA,0013</b>					
	0001	6355301UK3265N	1900	1900	S
<b>PZ PADRE J MARIANA,0001</b>					
	0000	3550004UK4235S	1962	1962	S
<b>PZ PADRE J MARIANA,0002</b>					

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0000	3550005UK4235S	1997	1997	S
<b>PZ PADRE J MARIANA,0003</b>					
	0001	3550006UK4235S	1940	1940	S
	0002	3550006UK4235S	1940	1940	S
<b>PZ PADRE J MARIANA,0004</b>					
	0001	3550007UK4235S	1955	1955	S
	0001	3550007UK4235S	1955	1955	S
	0001	3550007UK4235S	1955	1955	S
	0001	3550007UK4235S	1955	1955	S
	0002	3550007UK4235S	1955	1955	S
	0002	3550007UK4235S	1955	1955	S
	0002	3550007UK4235S	1955	1955	S
	0002	3550007UK4235S	1955	1955	S
<b>PZ PADRE J MARIANA,0005</b>					
	0001	3550008UK4235S	1920	1920	S
<b>PZ PADRE J MARIANA,0006</b>					
	0001	3550009UK4235S	1945	1945	S
	0001	3550009UK4235S	1945	1945	S
	0001	3550009UK4235S	1945	1945	S
	0002	3550009UK4235S	1945	1945	S
	0002	3550009UK4235S	1945	1945	S
	0002	3550009UK4235S	1945	1945	S
<b>PZ PADRE J MARIANA,0007</b>					
	0001	3550010UK4235S	1945	1945	S
	0001	3550010UK4235S	1945	1945	S
	0001	3550010UK4235S	1945	1945	S
	0001	3550010UK4235S	1945	1945	S
	0001	3550010UK4235S	1945	1945	S
	0001	3550010UK4235S	1945	1945	S
	0002	3550010UK4235S	1945	1945	S
	0002	3550010UK4235S	1945	1945	S
	0002	3550010UK4235S	1945	1945	S
	0002	3550010UK4235S	1945	1945	S
	0002	3550010UK4235S	1945	1945	S
	0002	3550010UK4235S	1945	1945	S
<b>PZ PADRE J MARIANA,0011</b>					
	0001	3650001UK4235S	1958	1958	S
	0002	3650001UK4235S	1958	1958	S
<b>PZ PAN,0001</b>					
	0001	3549001UK4234N	1900	1900	S
<b>PZ PAN,0010</b>					
	0001	3649207UK4234N	1927	1927	S
<b>PZ RELOJ,0004</b>					
	0001	3752008UK4235S	1900	1900	S
	0002	3752008UK4235S	1900	1900	S
	0003	3752008UK4235S	1900	1900	S
<b>PZ RELOJ,0009</b>					

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0001	3651135UK4235S	1900	1900	S
	0001	3651135UK4235S	1900	1900	S
	0002	3651135UK4235S	1900	1900	S
	0002	3651135UK4235S	1900	1900	S
<b>PZ RELOJ,0010</b>					
	0002	3651136UK4235S	1900	1900	S
	0003	3651136UK4235S	1900	1900	S
<b>PZ RELOJ,0011</b>					
	0001	3651137UK4235S	1900	1900	S
<b>PZ RELOJ,0012</b>					
	0000	3651101UK4235S	2005	2005	S
<b>PZ SALVADOR,0003</b>					
	0001	3452002UK4235S	1980	1980	S
	0002	3452002UK4235S	1921	1921	S
	0003	3452002UK4235S	1980	1980	S
	0004	3452002UK4235S	1980	1980	S
<b>PZ SAN ANDRES,0000</b>					
	0001	3250801UK4235S	1900	1900	S
<b>PZ SAN ANDRES,0001</b>					
	0001	3251018UK4235S	1900	1900	S
<b>PZ SAN ANDRES,0004</b>					
	0001	3151012UK4235S	1900	1900	S
	0002	3151012UK4235S	1900	1900	S
	0003	3151012UK4235S	1900	1900	S
<b>PZ SAN ANDRES,0005</b>					
	0000	3151013UK4235S	1900	1900	S
<b>PZ SAN ANDRES,0012</b>					
	0000	3250029UK4235S	1972	1972	
<b>PZ SAN ANDRES,0013</b>					
	0002	3250030UK4235S	1940	1940	S
<b>PZ SAN ESTEBAN,0011</b>					
	0001	3148003UK4234N	1960	1960	S
	0002	3148003UK4234N	1960	1960	S
	0003	3148003UK4234N	1960	1960	S
	0004	3148003UK4234N	1960	1960	S
<b>PZ SAN JERONIMO,0001</b>					
	0001	3848801UK4234N	1900	1900	S
<b>PZ SAN JERONIMO,0005</b>					
	0001	3749002UK4234N	1900	1900	S
	0002	3749002UK4234N	1900	1900	S
	0003	3749002UK4234N	1900	1900	S
<b>PZ SAN MIGUEL,0010</b>					
	0001	3453004UK4235S	1900	1900	S
	0002	3453004UK4235S	1900	1900	S
<b>PZ SAN MIGUEL,0012</b>					

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0001	3453005UK4235S	1900	1900	S
<b>PZ SAN PEDRO,0004</b>					
	0001	3750003UK4235S	1900	1900	S
	0002	3750003UK4235S	1900	1900	S
<b>PZ SAN PEDRO,0007</b>					
	0001	3751302UK4235S	1900	1900	S
	0002	3751302UK4235S	1900	1900	S
	0003	3751302UK4235S	1900	1900	S
<b>PZ SANTIAGO,0001</b>					
	0001	3653102UK4235S	1900	1900	S
	0002	3653102UK4235S	1900	1900	S
<b>PZ SANTIAGO,0005</b>					
	0001	3754701UK4235S	1900	1900	S
<b>PZ TINAJONES,0002</b>					
	0000	3455006UK4235N	1972	1972	
<b>PZ TINAJONES,0008</b>					
	0000	3555213UK4235N	2008	2008	S
	0000	3555213UK4235N	1950	1950	S
<b>PZ VILLATOYA,0003</b>					
	0001	3651504UK4235S	1900	1900	S
<b>TR CERRO,0003</b>					
	0001	2553014UK3225S	1972	1972	
	0002	2553014UK3225S	1972	1972	
<b>TR SAN BENITO,0005</b>					
	0001	3550502UK4235S	1936	1936	S
	0001	3550502UK4235S	1936	1936	S
<b>TR SAN JERONIMO,0005</b>					
	0001	3849605UK4234N	1900	1900	S
	0002	3849605UK4234N	1900	1900	S
<b>TR SANTIAGO,0001</b>					
	0001	3653101UK4235S	1900	1900	S
	0002	3653101UK4235S	1900	1900	S
<b>TR TOLEDILLO,0003</b>					
	0001	2655005UK3225N	1972	1972	
<b>UR LA PASTERA,0032</b>					
	0002	2966704UK4226N	1972	1972	
	0002	2966704UK4226N	1972	1972	
<b>UR LOS CAÑOS,0097</b>					
	0001	4679910UK4247N	1972	1972	
	0001	4679910UK4247N	1972	1972	
	0001	4679910UK4247N	1972	1972	
<b>UR LOS CAÑOS,0099</b>					
	0002	4679912UK4247N	1972	1972	
	0003	4679912UK4247N	1972	1972	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
<b>UR MATAHOMBRES,0063</b>					
	0001	2562803UK4226S	1967	1967	
	0001	2562803UK4226S	1967	1967	
<b>UR PIEDRAS MUCHAS,0103</b>					
	0002	3178504UK4237N	1972	1972	
	0002	3178504UK4237N	1972	1972	
	0003	3178504UK4237N	1972	1972	
	0003	3178504UK4237N	1972	1972	
<b>UR PIEDRAS MUCHAS,0104</b>					
	0001	3178501UK4237N	1972	1972	
	0002	3178501UK4237N	1972	1972	
	0003	3178501UK4237N	1972	1972	
<b>,0000</b>					
	0001	45166A00400010	1970	1970	S
	0001	45166A00400010	1970	1970	S
	0001	45166A00400010	1970	1970	S
<b>,0000</b>					
	0001	45166A00600001	1995	1995	S
	0002	45166A00600001	1910	1910	S
	0003	45166A00600001	1970	1970	S
	0004	45166A00600001	1910	1910	S
	0005	45166A00600001	1980	1980	S
	0006	45166A00600001	1970	1970	S
<b>,0000</b>					
	0001	45166A00700004	1967	1967	
<b>,0000</b>					
	0001	45166A00700199	1972	1972	
	0002	45166A00700199	1972	1972	
	0003	45166A00700199	1972	1972	
<b>,0000</b>					
	0001	45166A00700206	1972	1972	
	0001	45166A00700206	1972	1972	
<b>,0000</b>					
	0001	45166A00700252	1972	1972	
	0002	45166A00700252	1972	1972	
<b>,0000</b>					
	0001	45166A00700263	1967	1967	
<b>,0000</b>					
	0001	45166A00700264	1967	1967	
	0001	45166A00700264	1967	1967	
<b>,0000</b>					
	0002	45166A00700376	1972	1972	
	0002	45166A00700376	1972	1972	
<b>,0000</b>					
	0001	45166A00817105	1967	1967	

<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0002	45166A00817105	1967	1967	
<b>,0000</b>					
	0001	45166A00821105	1967	1967	
<b>,0000</b>					
	0001	45166A00822016	1967	1967	
	0001	45166A00822016	1967	1967	
<b>,0000</b>					
	0001	45166A00834105	1972	1972	
<b>,0000</b>					
	0001	45166A00839105	1967	1967	
<b>,0000</b>					
	0001	45166A01600016	1972	1972	
	0003	45166A01600016	1972	1972	
	0004	45166A01600016	1972	1972	
<b>,0000</b>					
	0001	45166A01600024	1967	1967	
	0002	45166A01600024	1967	1967	
<b>,0000</b>					
	0001	45166A01600046	1972	1972	
<b>,0000</b>					
	0000	45166A01600134	1967	1967	
<b>,0000</b>					
	0001	45166A01800170	1972	1972	
<b>,0000</b>					
	0001	45166A01800328	1967	1967	
<b>,0000</b>					
	0001	45166A01800356	1972	1972	
	0001	45166A01800356	1972	1972	
	0001	45166A01800356	1972	1972	
	0001	45166A01800356	1972	1972	
	0002	45166A01800356	1972	1972	
	0002	45166A01800356	1972	1972	
	0002	45166A01800356	1972	1972	
	0002	45166A01800356	1972	1972	
<b>,0000</b>					
	0001	45166A01800357	1972	1972	
	0001	45166A01800357	1972	1972	
	0002	45166A01800357	1972	1972	
	0002	45166A01800357	1972	1972	
<b>,0000</b>					
	0001	45166A01900075	1972	1972	
<b>,0000</b>					
	0001	45166A02100003	1960	1960	S
	0001	45166A02100003	1960	1960	S
	0002	45166A02100003	1960	1960	S

<b>SITUACIÓN</b>					
<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>	
0002	45166A02100003	1960	1960	S	
0004	45166A02100003	1960	1960	S	
0004	45166A02100003	1960	1960	S	
<b>,0000</b>					
0001	45166A02400002	1967	1967		
0002	45166A02400002	1967	1967		
0003	45166A02400002	1967	1967		
<b>,0000</b>					
0001	45166A02400008	1979	1979	S	
0001	45166A02400008	1979	1979	S	
0002	45166A02400008	1979	1979	S	
0002	45166A02400008	1979	1979	S	
0003	45166A02400008	1979	1979	S	
0003	45166A02400008	1979	1979	S	
0004	45166A02400008	1979	1979	S	
0004	45166A02400008	1979	1979	S	
<b>,0000</b>					
0001	45166A02400040	1959	1959	S	
0002	45166A02400040	1959	1959	S	
<b>,0000</b>					
0001	45166A02400043	1972	1972		
0002	45166A02400043	1972	1972		
<b>,0000</b>					
0001	45166A02400057	1967	1967		
<b>,0000</b>					
0001	45166A02400067	1967	1967		
0002	45166A02400067	1967	1967		
0003	45166A02400067	1967	1967		
<b>,0000</b>					
0001	45166A02400095	1972	1972		
0001	45166A02400095	1972	1972		
<b>,0000</b>					
0001	45166A02400099	1967	1967		
0001	45166A02400099	1967	1967		
<b>,0000</b>					
0001	45166A02400102	1967	1967		
<b>,0000</b>					
0001	45166A02700027	1972	1972		
0001	45166A02700027	1972	1972		
0001	45166A02700027	1972	1972		
0002	45166A02700027	1972	1972		
0002	45166A02700027	1972	1972		
0002	45166A02700027	1972	1972		
<b>,0000</b>					
0001	45166A03000052	1965	1965	S	
0002	45166A03000052	1999	1999	S	



<b>SITUACIÓN</b>	<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>
	0003	45166A03000052	1970	1970	S
<b>,0000</b>					
	0001	45166A03000154	1967	1967	
	0002	45166A03000154	1967	1967	
<b>,0000</b>					
	0001	45166A03000163	1967	1967	
	0001	45166A03000163	1967	1967	
	0002	45166A03000163	1967	1967	
	0002	45166A03000163	1967	1967	
<b>,0000</b>					
	0001	45166A03000179	1967	1967	
	0001	45166A03000179	1967	1967	
	0003	45166A03000179	1967	1967	
	0003	45166A03000179	1967	1967	
<b>,0952</b>					
	0001	45166A00200361	1942	1942	S
	0002	45166A00200361	1942	1942	S
	0003	45166A00200361	1942	1942	S
<b>DS DISEMINADO,0000</b>					
	0001	45166A02810042	1902	1902	S
	0002	45166A02810042	1945	1945	S
	0003	45166A02810042	1945	1945	S
<b>DS DISEMINADO,0927</b>					
	0001	45166A00110243	1940	1940	S
	0002	45166A00110243	1940	1940	S
<b>DS DISEMINADO,0966</b>					
	0003	45166A00200375	1972	1972	
	0003	45166A00200375	1972	1972	
	0004	45166A00200375	1972	1972	
	0004	45166A00200375	1972	1972	
<b>DS DISEMINADO,0976</b>					
	0003	45166A00200314	1972	1972	
	0003	45166A00200314	1972	1972	
	0004	45166A00200314	1972	1972	
	0004	45166A00200314	1972	1972	
	0005	45166A00200314	1972	1972	
	0005	45166A00200314	1972	1972	
<b>DS DISEMINADO,1289</b>					
	0001	45166A03200004	1986	1986	S
	0001	45166A03200004	1986	1986	S
	0001	45166A03200004	1986	1986	S
	0002	45166A03200004	1948	1948	S
	0002	45166A03200004	1948	1948	S
	0002	45166A03200004	1948	1948	S
	0003	45166A03200004	1986	1986	S
	0003	45166A03200004	1986	1986	S
	0003	45166A03200004	1986	1986	S

<b>SITUACIÓN</b>					
<b>UNIDAD CONSTRUCTIVA</b>	<b>REFERENCIA</b>	<b>AÑO</b>	<b>ANTIGUEDAD</b>	<b>PROT. POM</b>	
0004	45166A03200004	1986	1986	S	
0004	45166A03200004	1986	1986	S	
0004	45166A03200004	1986	1986	S	
0005	45166A03200004	1990	1990	S	
0005	45166A03200004	1990	1990	S	
0005	45166A03200004	1990	1990	S	
0006	45166A03200004	1990	1990	S	
0006	45166A03200004	1990	1990	S	
0006	45166A03200004	1990	1990	S	
0007	45166A03200004	1980	1980	S	
0007	45166A03200004	1980	1980	S	
0007	45166A03200004	1980	1980	S	
0009	45166A03200004	1970	1970	S	
0009	45166A03200004	1970	1970	S	
0009	45166A03200004	1970	1970	S	
<b>DS DISEMINADO,1335</b>					
0001	45166A02400028	1967	1967		
0001	45166A02400028	1967	1967		
0002	45166A02400028	1967	1967		
0002	45166A02400028	1967	1967		
0003	45166A02400028	1967	1967		
0003	45166A02400028	1967	1967		
0004	45166A02400028	1967	1967		
0004	45166A02400028	1967	1967		
<b>DS DISEMINADO,1523</b>					
0001	45166A02000031	1967	1967		
<b>DS DISEMINADO,1533</b>					
0001	45166A01610040	1972	1972		
0002	45166A01610040	1972	1972		
0003	45166A01610040	1972	1972		
0004	45166A01610040	1972	1972		
0005	45166A01610040	1972	1972		
<b>DS DISEMINADO,1634</b>					
0003	45166A00700256	1972	1972		
0003	45166A00700256	1972	1972		
0003	45166A00700256	1972	1972		
0003	45166A00700256	1972	1972		
<b>DS DISEMINADO,1651</b>					
0007	45166A00200396	1972	1972		